


KLAST

www.klasthome.com



MOURE

Ref: GA-0012


1/8

-V1.0-


KLAST

www.klasthome.com

MATERIAL



A x4 PC




B x3 PC




C x2 PC



D x16 PC



E x12 PC



M4x20 mm
F x48 PC



M6x70 mm
G x24 PC



M6x20 mm
H x24 PC



M6
I x24 PC



J x1 PC




K x3 PC




L x2 PC

STEP 1



STEP 2




MOURE

Ref: GA-0012


KLAST

www.klasthome.com


STEP 3




STEP 4



STEP 5



STEP 6




MOURE

Ref: GA-0012


KLAST

www.klasthome.com


STEP 7




STEP 8



STEP 9



STEP 10




MOURE

Ref: GA-0012


KLAST

www.klasthome.com


STEP 11




STEP 12



STEP 13



STEP 14




MOURE

Ref: GA-0012


KLAST

www.klasthome.com


STEP 7




STEP 8



STEP 9



STEP 10




MOURE

Ref: GA-0012


KLAST

www.klasthome.com


STEP 11




STEP 12



STEP 13



STEP 14




MOURE

Ref: GA-0012


KLAST

www.klasthome.com



STEP 15



STEP 16



STEP 17



MOURE

Ref: GA-0012