


KLAST

www.klasthome.com



LIVORNO

Ref: SC-0034


1/14

-V1.0-

KLAST

www.klasthome.com

MATERIAL



LIVORNO

Ref: SC-0034

KLAST

www.klasthome.com


MATERIAL



A x32 PC



B x36 PC




C x32 PC




D x42 PC




E x30 PC




F x1 PC




I3 x8 PC



P x10 PC



K x4 PC



N x1 PC




O x10 PC



M3.5x12 mm

V1 x8 PC



U x6 PC


LIVORNO

Ref: SC-0034

KLAST

www.klasthome.com

STEP 1




LIVORNO

Ref: SC-0034

KLAST

www.klasthome.com

STEP 2



LIVORNO

Ref: SC-0034


5/14

-V1.0-


KLAST

www.klasthome.com

STEP 3



STEP 4



LIVORNO

Ref: SC-0034


6/14

- V1.0 -

KLAST

www.klasthome.com

STEP 5



LIVORNO

Ref: SC-0034


7/14

-V1.0-

KLAST

www.klasthome.com

STEP 6




LIVORNO

Ref: SC-0034

KLAST

www.klasthome.com

STEP 7



LIVORNO

Ref: SC-0034


9/14

-V1.0-

KLAST

www.klasthome.com

STEP 8





LIVORNO

Ref: SC-0034

www.klasthome.com

Diagram illustrating the assembly of the slats (16, 15, 17, 18) using screws. A detailed view of the screw is shown on the left, labeled $\text{Ø} \times 10$.




Ref: SC-0034

KLAST

www.klasthome.com

STEP 10




LIVORNO

Ref: SC-0034

KLAST

www.klasthome.com

STEP 11




LIVORNO

Ref: SC-0034

KLAST


www.klasthome.com

STEP 12



⚠ OBLIGATORY FIX ON THE WALL

The needed hardware for the junction wall/furniture depends of the nature of the wall and is not provide.



LIVORNO

Ref: SC-0034