


KLAST

www.klasthome.com



TIKA

Ref: EB-0001

1/7

-V1.0-

KLAST

www.klasthome.com

MATERIAL



M6x40 mm
A x16 PC




Ø15x9 mm
B x16 PC



C x1 PC



D x1 PC




TIKA

Ref: EB-0001


KLAST

www.klasthome.com

STEP 1



STEP 2




TIKA

Ref: EB-0001


KLAST

www.klasthome.com

STEP 3



STEP 4




TIKA

Ref: EB-0001


KLAST

www.klasthome.com

STEP 5



STEP 6



TIKA

Ref: EB-0001

www.klasthome.com


This diagram illustrates the assembly of a four-sided enclosure. It shows five components: a base panel (1), two side panels (3 and 4), and two end panels (2 and 5). The base panel (1) is shown at the bottom. The side panels (3 and 4) are positioned on the right and left sides, respectively, and feature pre-drilled holes for screws. The end panels (2 and 5) are positioned at the front and back. Arrows indicate the assembly sequence: panel 2 is attached to the base, followed by panel 3, then panel 4, and finally panel 5 is attached to the top edge of the structure.

Ref: EB-0001


KLAST

www.klasthome.com

STEP 9



STEP 10



TIKA

Ref: EB-0001